



Cavanaghs Charleville
Limerick Road
Rathgoggan Middle
Charleville
Co. Cork
CORK
00353 63 30300
service@cavanaghs.com
http://www.cavanaghs.com/

Cavanaghs Charleville Vehicle Healthcheck

VHC Date 16-04-2021
Make F
Model MONDEO 1.5TDCI
TITANIUM 5DR 12
Reg. No 162C104
Mileage 90205
Job Card no. 45528
Customer NOT AVAILABLE
Telephone
Mobile
VIN WF0EXXWPCEGB16579



| Wheels & Tyres | Green | Amber | Red | Report & Recommendations | Depths(mm) | | | Identified | Authorised | Auth |
|--|--------------|--------------|------------|--|------------|--------|-------|-------------------|-------------------|-------------|
| | | | | | Outer | Middle | Inner | | | |
| N/S Front Tyre | ✓ | | | (UNKNOWN 235, 50, 17, W) | 4.9 | 4.9 | 4.9 | 0.00 € | 0.00 € | No |
| O/S Front Tyre | ✓ | | | (UNKNOWN 235, 50, 17, W) | 4.7 | 4.7 | 4.7 | 0.00 € | 0.00 € | No |
| N/S Rear Tyre | | | ✓ | (UNKNOWN 235, 50, 17, W) | 1.6 | 2.6 | 2.0 | 18.45 € | 0.00 € | No |
| O/S Rear Tyre | | | ✓ | (UNKNOWN 235, 50, 17, W) | 1.6 | 1.6 | 1.6 | 18.45 € | 0.00 € | No |
| Spare Tyre | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Spare Tyre equipment | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Wheel Alignment | | | ✓ | Four Wheel Alignment required. | | | | 45.40 € | 0.00 € | No |
| External/Drive In Inspection | Green | Amber | Red | Report & Recommendations | | | | Identified | Authorised | Auth |
| Dents | ✓ | ✓ | | Various marks on vehicle | | | | 0.00 € | 0.00 € | No |
| Scratch | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Wheels | ✓ | | ✓ | Shake from steering at 100kmh possible buckled wheel or balancing | | | | 0.00 € | 0.00 € | No |
| Additional Scratch | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Glass/Mirrors/Door Locks | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Other Dents | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Wheel | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Brakes Clutch / Transmission OP | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Glass/Mirrors/Door Locks | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Engine Noise/ Smoke | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Brakes/Clutch/Transmission OP | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Engine Noise/Smoke | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Internal/Lamps/Electrics | Green | Amber | Red | Report & Recommendations | | | | Identified | Authorised | Auth |
| Mandatory Lights Front (external) | ✓ | | ✓ | Front park bulb blown | | | | 9.65 € | 0.00 € | No |
| Mandatory Lights Rear (external) | ✓ | | ✓ | Drivers rear outer lamp holding moisture | | | | 28.94 € | 0.00 € | No |
| Front Wipers/Flat Blades | ✓ | | ✓ | Front Wipers recommended - streaking the screen. | | | | 0.00 € | 0.00 € | No |
| Horn/Wipers/Washers | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Air Con/Heating/Ventilation System | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Internal Conditions | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Additional Warning Lamps | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Service Indicator Light On | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Odour/Pollen Filter | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Internal Condition | ✓ | | ✓ | Steering wheel leather damaged and should be replaced. | | | | 0.00 € | 0.00 € | No |
| Warning Lamps | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Underbonnet | Green | Amber | Red | Report & Recommendations | | | | Identified | Authorised | Auth |
| Engine Oil Level/Anti Freeze | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Water/Oil/Fluid Leaks | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Alternator Belt/Battery | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Power Steering Fluid | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Timing Belt | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Fuel System | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Brakes & Hubs | Green | Amber | Red | Report & Recommendations | | | | Identified | Authorised | Auth |
| Master Cylinder/Servo/Fluid | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Brake Fluid Boiling Point | ✓ | | ✓ | Ford recommends Brake Fluid Change every 2 years/30.000kms. Brake fluid absorbs moisture from the atmosphere which will reduce its boiling point over time and therefore reducing its effectiveness of the braking system. | | | | 43.41 € | 0.00 € | No |
| Front Brakes | ✓ | | | Front brakes recently replaced | | | | 0.00 € | 0.00 € | No |
| Rear Brakes | ✓ | | ✓ | Rear pads 3mm 100% worn | | | | 52.10 € | 0.00 € | No |
| Wheel Bearings | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Hoses/Pipes/Cables | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Underside | Green | Amber | Red | Report & Recommendations | | | | Identified | Authorised | Auth |
| Exhaust System/Catalyst | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Steering | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Front Suspension | ✓ | | | | | | | 0.00 € | 0.00 € | No |
| Rear Suspension | ✓ | | | | | | | 0.00 € | 0.00 € | No |

Note: This report is of visual examination only - further checks may be necessary to determine full extent of requirements.

| | | | | | | | |
|-----------------------------------|-------|-------|-----|--------------------------|------------|------------|------|
| Other Front Suspension | ✓ | | | | 0.00 € | 0.00 € | No |
| Driveshafts/Oil Leaks | ✓ | | | | 0.00 € | 0.00 € | No |
| Pre-Conditionining/Extra Value | Green | Amber | Red | Report & Recommendations | Identified | Authorised | Auth |
| Pan- European Roadside Assistance | ✓ | | | | 0.00 € | 0.00 € | No |
| Other Items | ✓ | | | | 0.00 € | 0.00 € | No |
| Next Service Due Date | ✓ | | ✓ | Full service reccomended | 138.92 € | 0.00 € | No |
| Next NCT Due Date | ✓ | | | | 0.00 € | 0.00 € | No |
| Miscellaneous | ✓ | | | | 0.00 € | 0.00 € | No |
| eCHECK Video | Green | Amber | Red | Report & Recommendations | Identified | Authorised | Auth |
| eCheck Video | ✓ | | | Video uploaded | 0.00 € | 0.00 € | No |

Technician: Dylan O Leary

Total Identified **Total Authorised**

Service Advisor :

355.32 € 0.00 €

Quality control:

Customer signature

Note: Total Values Include VAT

